



Thor Motor Coach Recall Repair Instructions

Recall # 17V-162

Description/Title: **Gas Wiper Arm**

Affected Product Line(s): Certain Model Year 2014, 2015, & 2016 ACE, Challenger, Daybreak, Hurricane, Miramar, Outlaw, and Windsport motorhomes

Service Campaign # : **RC000131**

Released Date: **4/12/2017**

Failure Code: **TMCRC80460V**

Document Date: **4/12/2017**

Time Allowed: **0.2 hr**

Document Revision: **A**

It has been decided that the windshield wiper systems on certain 2014, 2015, & 2016 model year gas class A motorhomes may have been incorrectly installed and secured at the time of manufacture.

NOTE: TAKE CARE WHEN REMOVING AND REINSTALLING ITEMS. TMC WILL NOT COVER ANY DAMAGES INCURRED DURING THE COMPLETION OF THE PROCESS.

Instructions

Locate the acorn nut at the base of the wiper arm.



Tighten it to 12-14 nm of torque (approximately 8.85-10.32 ft-lbs).

Repeat for other wiper arm