













REV	DESCRIPTION	DATE	BY	ECN	ALL CONNECTORS SHOWN ARE LOAD VIEW UNLESS OTHERWISE NOTED.	THOR MOTOR COACH
0	INITIAL RELEASE	01/08/15	DRC	11258	ALL WIRE MUST BE 125°C UNLESS OTHERWISE NOTED.	DRWN BY: DRC, SHEET: 1 OF 1, DATE: 01/08/15
1	CHANGE LIGHTS AND ADD SWITCH	3/24/15	MSH	11442	LOOM AS NOTED BY —	DESCRIPTION: HARNESS, CHASSIS 2016
2	ADDED WIRE ON BED LIGHTS AND BED FAN, REMOVED WIRE FROM P3-15 (IGNITION)	04/23/15	DRC	11588	LOOM SHOULD HAVE RATING OF 125°C MINIMUM TOLERANCES.	MODEL: CLASS C 31L
3	ADDED WIRES FOR SOFFIT LTS, AND SPEAKER PLUG	06/19/15	DRC	11519	1" = 50"	© CONFIDENTIAL AND PROPRIETARY INFORMATION OF THOR MOTOR COACH. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT OUR EXPRESSED WRITTEN CONSENT IS PROHIBITED.
4	ADDED WIRE TO SOFFIT LIGHTS AND BLACK HEATER	08/14/15	DRC	—	REFERENCE TEE1333.XLS FOR CUTLIST	DRAWING NUMBER: TEE1338, REVISION: 4
					SPECIAL NOTES:	





REV	DESCRIPTION	DATE	BY	ECN	ALL CONNECTORS SHOWN ARE LOAD VIEW UNLESS OTHERWISE NOTED. ALL WIRE MUST BE 125°C UNLESS OTHERWISE NOTED. LOOM AS NOTED BY _____ LOOM SHOULD HAVE RATING OF 125°C MINIMUM TOLERANCES: ±1" ±30" ±2" ±30" REFERENCE: TEE1339 XLS FOR CUTLIST	THOR MOTOR COACH
0	INITIAL RELEASE	01/09/15	DRC	11258		DRWN BY: DRC, SHEET 1 OF 1, DATE 01/09/15
1	CHANGE LIGHTS AND ADD SWITCH	3/24/15	MSH	11442		DESCRIPTION: HARNESS, RIGHT SIDE
2	ADDED WIRE TO SINK LIGHT WIRES, REMOVED TV LOCKOUT	04/24/15	DRC	11442		MODEL: CLASS C 31L
3	ADDED 10" TO SYSTEMS PANEL WIRES	05/13/15	DRC	-		© CONFIDENTIAL AND PROPRIETARY INFORMATION OF THOR MOTOR COACH. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT OUR EXPRESSED WRITTEN CONSENT IS PROHIBITED.
4	MOVED SINK LT #1 DROP	06/19/15	DRC	11519		DRWN BY: TEE1339, REVISION 7
5	ADD BUNK LIGHT SWITCH AND SECOND LIGHT	08/06/15	SDH	11760		
6	ADDED RANGE HOOD WIRES FOR FRASERWAY RENTALS	03/09/16	DRC	12235		
7	MOVED ANTENNA BOOST DROP	04/28/16	DRC	-		



REV	DESCRIPTION	DATE	BY	ECN	ALL CONNECTORS SHOWN ARE LOAN VIEW UNLESS OTHERWISE NOTED. ALL WIRE MUST BE 125°C UNLESS OTHERWISE NOTED. LOOM AS NOTED BY — LOOM SHOULD HAVE RATING OF 125°C MINIMUM. TOLERANCES: ± 1" ± .50" ± 2" ± .50" REFERENCE TEE1339.XLS FOR CUTLIST	THOR MOTOR COACH
0	INITIAL RELEASE	01/09/15	DRC	11258		DRWN BY: DRC, SHEET 1 OF 1, DATE 01/09/15
1	CHANGE LIGHTS AND ADD SWITCH	3/24/15	MSH	11442		DESCRIPTION: HARNESS, RIGHT SIDE
2	ADDED WIRE TO SINK LIGHT WIRES, REMOVED TV LOCKOUT	04/24/15	DRC	11442		MODEL: CLASS C 31L
3	ADDED 10" TO SYSTEMS PANEL WIRES	05/13/15	DRC	—		DATE: 01/09/15
4	MOVED SINK LT #1 DROP	06/19/15	DRC	11519		CLASS C 31L
5	ADD BUNK LIGHT SWITCH AND SECOND LIGHT	08/06/15	SDH	11760		DATE: 01/09/15
6	ADDED RANGE HOOD WIRES FOR FRASERWAY RENTALS	03/09/16	DRC	12235		CLASS C 31L
7	MOVED ANTENNA BOOST DROP	04/28/16	DRC	—		DATE: 01/09/15

SPECIAL NOTES:

© CONFIDENTIAL AND PROPRIETARY INFORMATION OF THOR MOTOR COACH. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT OUR EXPRESSED WRITTEN CONSENT IS PROHIBITED.

DRWN BY: TEE1339, REVISION: 7